



Monday, Inspection Date, Year Inspector Name

Phone email@npiinspect.com

Inspection Date: Date

Inspector: Name Inspector Phone: #



GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION :

Property Occupied : No Estimated Age Of Property : <1 Year(s) Property Faces : In North In South East In West	Temperature : 48 F Weather : ☑ Sunny
Type of Property : ☑ Single-Family	Soil Conditions : ☑ Dry
Primary Construction :	Persons Present :
☑ Wood	☑ Buyer ☑ Buyer's Agent

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE)	The item/system was performing its intended function at the time of the inspection.
MAR (MARGINAL)	The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.
NI (NOT INSPECTED)	The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal conditions and no representations of whether or not it was functioning as intended were made.
NP (NOT PRESENT)	The item/system does not exist or was visually concealed at the time of the inspection.
DEF (DEFICIENT)	The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION :

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, not every item was or could be inspected. Please read the entire report carefully, ask your inspector any questions you might have and obtain estimates or discuss noted items with a contractor before closing.

Email: email@npiweb.com

Sample Report, 12345 Property Address Dr, City, State, Zip

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 GRADING / DRAINAGE

 Termite bait stations were not observed around the perimeter of the building, however a termite inspection and/or evaluation of an existing system is beyond the scope of a home inspection. Recommend builder inquiry if termite and/or pest control systems are responsibility of HOA or Owner.

• Final construction cleanup, including garage and interior.

2 DECKS / BALCONY

 Isolated areas of nails protruding above the deck boards, along with some splintering of the deck boards. Both items could present potential safety concerns and correction is recommended.

3 ROOFING

 There appeared to be some isolated installation debris (abandoned roofing nails, shingle cut-outs) scattered on the rear slope of the roof. Recommend further review and removal of any installation debris.

4 WINDOWS

Window screen was missing at one of the windows.

Inspector: Name

Inspector Phone: #

 Window latches may need some minor adjustments. Several latches were difficult to close, and one window latch in the family room was unable to close.

5 EXTERIOR DOORS

 Daylight gaps were present at the front and deck doors. Doors may require adjustments or additional weather strip shims.

Inspection Date:



MARGINAL

DEFICIENT

MARGINAL

MARGINAL

MARGINAL



6 OVERHEAD GARAGE DOORS

• The automatic garage door opener may need adjustments, as during testing of the closing function the door would auto reverse upon contact with the concrete slab.

• Although not required, consider installation of manual hardware (lift handle) in order to safely operate the door when manual operation is necessary.

7 HEATING DISTRIBUTION - UNIT 1 GARAGE

Distribution

• Filter was slightly dirty. Recommend replacement at time of occupancy.

8 HEATING DISTRIBUTION - UNIT 2 ATTIC

Distribution

• Filter was slightly dirty. Recommend replacement at time of occupancy.

9 KITCHEN

Dishwasher/Cross Flow Protection

• Dishwasher drain line was leaking at the connection to the garbage disposal. Draining feature of the dishwasher was not further tested due to active leak and potential for interior water damage.

10 BATHROOM 3 - MAIN OWNERS

Sink/Faucet

• The left sink was draining slowly, suggesting there is a restriction in the drain pipe under the sink.

MAR (MARGINAL)The item/system was marginally acceptable. It performed its designed function at the time of the
inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.DEF (DEFICIENT)The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or
was hazardous at the time of the inspection.

MARGINAL

DEFICIENT

MARGINAL

MARGINAL

DEFICIENT



		ACC	MAR	NI	NP	DEF
DECIMA (DAL CONTA		ACC	MAK	INI	INP	DEF
DECKS / BALCONY	Recommend Repairs					
⊠Wood						

Comments:

Deck is constructed on brick columns and is bolted to the home. Deck joists are set in mechanical hangers. Overall, the deck is in good condition.

• Isolated areas of nails protruding above the deck boards, along with some splintering of the deck boards. Both items could present potential safety concerns and correction is recommended.



Decks / Balcony:



Decks / Balcony:



Decks / Balcony:




Decks / Balcony: Protruding Nails

Inspection Date: Date Inspector: Name Inspector Phone: #





Decks / Balcony: Splintering



Decks / Balcony:



Decks / Balcony: Splintering

					-	_	
			ACO	MAR	NI	NP	DEF
ROOFING		☑ Monitor C	ondition	Ø			
Age: 01 Year(s)	Design Life: 25-30 Year(s)	Layers: 1	100% Vi	sible			
☑ Visual From Ground	Asphalt / Composition	⊠Metal					

Comments:

Overall the roof covering is in functional and acceptable condition. Roof appears to be shedding water as designed. No active interior leaks detected. No visible wind or hail damage.

• There appeared to be some isolated installation debris (abandoned roofing nails, shingle cut-outs) scattered on the rear slope of the roof. Recommend further review and removal of any installation debris.

Leaks not always detectable.

Inspection Date: Inspector: Name Date Inspector Phone: # Email: email@npiweb.com

©1996-2023





Roofing:



Roofing: Installation Debris

Roofing:

Roofing:

Inspection Date: Date Inspector: Name Inspector Phone: #



Attic / Roof

Method of Inspection Physical Entry

80 % Visible

ATTIC FRAMING/SHEATHING

Plywood / Panel Board / OSB Trusses

Comments:

The home was a townhouse and had the proper firewall(s) installed in the attic area. The attic interior was visually examined for leaks and/or water stains. No cracked trusses, stains, or leaks were observed. H-clips were installed on sheathing seams. Framing/sheathing appeared to be functioning as designed, and appeared to be built within standards of practice for time of construction. All the framing and sheathing that was visible from the attic was acceptable at time of inspection.

Leaks not always detectable.



Attic Framing/Sheathing:



ACC MAR

 $\mathbf{\nabla}$

NI

NP

DEF

Attic Framing/Sheathing:

Inspection Date: Date Inspector: Name Inspector Phone: #



	F.T.N	MAIN MODULE OVERCURRENT	SY5
LOADCENTER TYPE: CH NEMA ENCLOSURE TYPE: 1 - INDOOR	ENCLOSED PANELBOARD RATING: 225 AMPS MAX. SEE MAIN BREAKER RATING. 120(240 VAC 1 PHASE 3 WIRE, 2089/120 VAC 3 WIRE, 50/60 HZ.	DEVICE BREAKER TYPE or CLASS FUSE	AT
SEE CASE SIDEWALL FOR FURTHER INFORMATI	ON, BUS RATING: 225 AURYS MAX. MAXIMUM SUM OF BREAKER RATINGS PER STAB: 200 A	NONE	
BREAKER INFORMATION MAIN BREAKERS (EATON TYPE): CSR, CSH (BRANCH BREAKERS (EATON TYPE): CH, CH	OR BACKFED TYPE CH (REQUIRES HOLD-DOWN KIT PER BELOW). CHAF, CHOF, CHAFOF, CHEP, CHSW, CHHID, CHT, CHP, CHM.	WITHOUT MAIN DISCONNECT	14
CHHM OR CHST. ADDITIONAL OR REPLACEMENT BREAKERS	SHALL BE OF THE SAME I ANUFACTURER AND TYPE AND SHALL OR OREATER THAN THE EXTERNIPTING RATING OF ANY CIRCUIT	CABLE TAP BOX	100
BREAKER INSTALLED. AUTOMATIC TRIP IS INDICATED BY A HANDL	E POSITION MIDWAY BETWEEN THE 'ON' AND 'OFF', MOVE	TYPE IMTB, 3MTB MAIN SWITCH	
HANDLE TO EXTREME "OFF", THEN TO "ON" INSTALLATION NOTES	MODULE TYPE 1MFS, 3MFS TYPE 18PS, 38PS	-	
SUITABLE FOR USE AS SERVICE FOR IDMEN	ACCORDANCE WITH ALL APPLICABLE LOCAL AND NATIONAL	MAIN BREAKER	
WHEN USED AS SERVICE EQUIPMENT, ANY GROUNDING, FOR EQUIPMENT GROUNDING #14-10 WIRES, MULTIPLE WIRES IN THE SAM	WIRE TERMINALS ARE E FOR (1) #14-4 OR UP TO (3)	TYPE IMP IMCB	
TERMINALS OTHER THAN BREAKER TERMIN SUITABLE FOR AL-CU WIRE WHEN SO MARK		14083	
ACCESSORIES BACKFED MAIN BREAKER HOLD DOWN KIT : CSR TYPE MAIN BREAKER FILLER PLATE : T			
FILLER PLATE TO CLOSE BRANCH OPENING MAIN LUG KIT FOR CONVERTIBLE PANELS : SUBFEED LUG KIT - CAT # CHPSE 125	S TYPE # CHEP SERVICE BARDER KIT TICSR300		-
# 5 - 20 NEUTRAL / GROUND LUGS : CAT # N		NONE	-11
# 6 - 300 NEUTRAL W BOND TAB LUGS CAT BONDING STREAM WE BOND TAB LUGS CAT	# NLP20 1" HUB: CAT # DS100H1 # NLP300 1-14" HUB: CAT # DS125H"		1
MECHANICAL INTERLOCK KIT: CAT # CHPM GROUND BARS : TYPE # GEKP RENOVATION TERMINAL BLOCK KIT: CAT # I		MAIN SWITCH MODULE TYPE 1MFS, 3MFS WITH CLASS T FUSE 1200A MAX	11
ASSEMBLED IN USA	www.eaton.com PUBS3441 R/N/ 02	** METER MODULE TYP	

Electrical:

PLUMBING

Water Service

☑ Water Public

☑ Shut Off Location: Garage

Sewage Service ☑ Sewage Public

Fuel Service

Shut Off Location: Rear Exterior

	ACC	MAR	NI	NP	DEF
SUPPLY PEX	Ø				
DRAINS \square_{PVC}	V				
EJECTOR PUMP				V	
VENTS PVC	V				

Comments:

Plumbing system and components appeared to be in acceptable condition at time of inspection. Water pressure at time of inspection was 65-70 psi (within recommended standards of 40-80 psi). The main interior shut-off and PRV (pressure reduction valve) are located in the garage above the water heater. The exterior hose bib shut-offs are located in the garage and under the sink at the basement bathroom. Plumbing cleanouts were observed in the driveway and at the right rear grounds by the driveway. The water meter/curb-stop is located street side at the left front grounds, and the gas meter is along the rear exterior of the building. The fire suppression system in this home was not operated/tested and is beyond the scope of this inspection. Fire suppression/sprinkler systems should be evaluated by a professional on a routine basis.

Main utility line, septic systems and gray water systems are excluded from this Inspection.

Inspection Date:	Inspector: Name	Email: email@npiweb.com
Date	Inspector Phone: #	





Plumbing:




Plumbing:



Plumbing:

Inspection Date: Date Inspector: Name Inspector Phone: #

nne: #



Plumbing:



Plumbing: Gas Meter



Plumbing:

Email: email@npiweb.com

©1996-2023





Heating Distribution - Unit 1 Garage:

HEATING DISTRIBUTION - UNIT 2 ATTIC

Monitor Condition

☑Ductwork	☑ Dirty Filter					
		ACC	MAR	NI	NP	DEF
DISTRIBUTION			M			
BLOWER		Ø				
CONTROLS/THERMOSTAT	(CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.)	Ø				
CIRCULATOR PUMP					V	

Comments:


Thermostat appeared to operate as designed at time of inspection. Adequate air flow was present. Recommend biannual cleaning of furnace and ductwork in order to maintain proper operation and to extend life expectancy of heating unit. Regular filter changing/cleaning is required as a part proper maintenance. Filter is sized at 16x25x1 and is located at the heating unit filter door.

• Filter was slightly dirty. Recommend replacement at time of occupancy.






Heating Distribution - Unit 2 Attic:



Heating Distribution - Unit 2 Attic:



Heating Distribution - Unit 2 Attic:



Heating Distribution - Unit 2 Attic:

			AC	CMAR	NI	NP	DEF
COOLING - UNIT 1	(UPPER)		E		V		
Brand: Lennox Design Life: 15+/- Year(s)	Model: 14ACXS024-230A22 SerialNo: 1919E41904	Size: 2.0 Ton	Age: 01 Year(s)				
⊠Electric	Outside Temperature too cold	to test					

Comments:

A/C unit should not be tested in cool mode with temperature below 65 degrees for fear of damaging compressor. Recommend further evaluation by a qualified professional when ambient air is warmer. The temperature splits could not be properly tested with the low temperatures. Determining correct size for an air conditioning system is beyond the scope of a home inspection. Clearances between the individual A/C units, and between the A/C and the fencing, may be inadequate.

Inspection Date: Inspector: Name Date

Inspector Phone: #





Cooling - Unit 1 (Upper):



Cooling - Unit 1 (Upper):



Cooling - Unit 1 (Upper):



Cooling - Unit 1 (Upper):

			[ACC	MAR	NI	NP	DEF
COOLING - UNIT 2 (BSMT/MAIN)			$\mathbf{\nabla}$				
Brand: Lennox Design Life: 15+/- Year(s)	Model: ML14XP1-024-230A01 SerialNo: 1919F46024	Size: 2.0 Ton	Age:	01 Yo	ear(s)			
☑Electric	☑ Heat Pump	Outside Temperature too c	old to test					

Comments:

Heat pump was operated in heat mode only. Unable to operate in cooling mode due to outdoor temperature below 65 degrees. Determining correct size for an air conditioning system is beyond the scope of a home inspection. Clearances between the individual A/C units, and between the A/C and the fencing, may be inadequate.

Inspection Date: Ins Date Ins

Inspector: Name Inspector Phone: #





Cooling - Unit 2 (Bsmt/Main):



Cooling - Unit 2 (Bsmt/Main):



Cooling - Unit 2 (Bsmt/Main):



Cooling - Unit 2 (Bsmt/Main):

KITCHEN	☑ Recommend Repairs	ACC	MAR	NI	NP	DEF
CEILINGS	*	Ø				
WALL(S)		Ø				
WINDOWS/TRIM					Ø	
WINDOW SCREENS					Ø	
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	RECOMMENDED.)	Ø				

Inspection Date: Date Inspector: Name Inspector Phone: #